



सिविल अभियान्त्रिक विभाग

पोस्ट श्रीनिवासनगर, मंगलूरु - 575 025

DEPARTMENT OF CIVIL ENGINEERING

POST SRINIVASNAGAR, MANGALURU - 575 025

30th October 2019

BUIDING SAFETY INSPECTION REPORT

This report is in response to the request made by the Principal, The Yenepoya School, NH-66, Jeppinamogaru, Mangaluru-575 007, vide letter dated 24.09.2019. They requested the HOD of Civil Engineering, NITK Surathkal, to inspect the building and issue the building safety certificate.

Accordingly, the undersigned visited the school on 30th September, 2019, verified the documents and inspected the building. The manager and staffs were present during the inspection. The documents verified include certificate of land, approved building plan, building license, school recognition certificate, compliance letter from Chief fire officer and the letter from CBSE, Delhi.

The building is located in survey No. 29-2AP, 28-1(P), 30-5B(P), 30-6(P), Jappinamogaru Village, Mangalore Taluk, Dakshina Kannada district. The building has been inspected in detail. All the load bearing structural components are strong and sound, with no indication of distress.

It is hereby certified that the building of the Yenepoya School, Mangaluru-575007 has been inspected on 30th September, 2019 and the building is structural safe and fit for occupancy.

(PRASHANTH M. H)
Assistant Professor

(PALANISAMY T)
Assistant Professor

(K. SWAMINATHAN)
Professor & Head

Craccuvenha
27/5/2021
Principal
The Yenepoya School
CBSE / Aff. / No. 830356
NH - 66, Jeppinamogaru
MANGALORE - 575 009
Ph: 0824 - 2241864

